$\underline{0}\,\underline{0}\,\underline{0}\,8$

From:

Karl Houskeeper

To:

GGalecki@archcoal.com

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

4/6/2009 2:35 PM

Subject:

March 2009 Inspection Report

Attachments: Skyline March 2009.pdf

Gregg,

Attached is the March 2009 inspection report for Skyline.

Thanks, Karl

autgoing C0070005



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection: Company Gregg Galecki Environmental Coordinator OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070005		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, March 12, 2009		
Start Date/Time:	3/12/2009 8:30:00 AM		
End Date/Time:	3/12/2009 2:00:00 PM		
Last Inspection:	Thursday, February 12, 2009		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: <u>Partly Cloudy, Temp. 27 Deg. F.</u> InspectionID Report Number: <u>1944</u>

Accepted by: jhelfric

3/24/2009

Permitee: CANYON FUEL COMPANY LLC
Operator: CANYON FUEL COMPANY LLC

Site: SKYLINE MINE

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Acreages	Mineral Ownership	Types of Operations		
Total Permitted	✓ Federal	✓ Underground		
Total Disturbed	✓ State	☐ Surface		
Phase I	☐ County	☐ Loadout		
Phase II	Fee Fee	Processing		
Phase III	☐ Other	Reprocessing		
	Total Permitted Total Disturbed Phase I Phase II	Total Permitted ✓ Federal Total Disturbed ✓ State Phase I County Fee		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature

Keener Environmental Scientist III

Date

Thursday, March 12, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070005

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Thursday, March 12, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	Y		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	•		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Thursday, March 12, 2009

Page 3 of 3

2. Signs and Markers

The Mine ID signs are at the point of public access to the permit area and contain the required information. All other signs and markers are in accordance with the coal rules.

4.a Hydrologic Balance: Diversions

The diversions are snow covered. Need to monitor the diversion leading from the storage sheds to the main access at the parking lot entrance. The diversion should be monitoried as the snow melts to assure that no obstructions to the diversion occur.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

As noted in the complete inspection on 02/12/2009 the fourth quarter 2008 pond Inspections were done December 31, 2008, no problems were noted. The reports for ponds 001, 002 and 003 did not contain the estimated sediment level. The reports need to be revised to show this information. The reports have bee revised, but still need a P.E. certification at which time they will be submitted to the Division.